# Advantage Home & Property Inspections LLC Property Inspection Report



522 Puka Puka Avenue, Somewhere Idaho Inspection prepared for: Mr. & Mrs. Sample Agent: Dominic Maricic - Home Inspector Pro

Inspection Date: 6/29/2009 Time: 9:00 am Age: 1982 Size: 2200 sq. ft. Weather: appx. 75 degrees Log Home

Inspector: Steven Degiulio License #NACHI07081104



National

Association of

Certified

Home

Inspectors

522 Puka Puka Avenue, Somewhere, Idaho

#### Summary of items of Concern

On the following page you will find a summary of the concerns of the property, as they relate to Safety, Maintenance, & Cosmetic issues, (non code), found during the Inspection. Please be sure to read the entire report.

The following report is based on an inspection of the visible portion of the structure; inspections may be limited due to access/ vegetation/personal items & possible weather (snow covered areas).

The ratings of said found items are of the Inspectors opinion (only). The items listed in black are of general maintenance and or cosmetic concerns. The items listed in **green** are of Safety or Critical concerns, & that may require further investigation or repairs & sooner attention than others, nor is the intent of the summary meant as a "punch list" or a list of repairs to be brought before the realtor/homeowner.

For your safety & liability, we recommend that you consult only qualified contractors for estimates & repairs.

Depending on your needs, and those who will be on this property, the items listed in the body of this report may be of greater concern to you than rated, again please be sure to read the entire report.

Thank you for choosing Advantage Home & Property Inspections. I hope you have found our services satisfactory. Please feel free to contact us at anytime if you have any questions or concerns, or if we can be of any further service to you. We hope you enjoy your new home & all the benefits that come with it! Sincerely, Steve DeGiulio (owner/inspector).

Inspected in accordance with the Standards of Practice of the National Association of Certified Home Inspectors, posted at www.nachi.org

## Report Summary

Exterior Areas				
Page 5 Item: 6	Grounds Electrical	<ul> <li>exposed romex wiring, (evidence of broken insulation)</li> <li>Consult qualified professional</li> </ul>		
Attic				
Page 9 Item: 2	Exhaust Vent	Bath exhaust fan does not vent to the exterior (causes moisture build up/possible dry rot) • Evidence of possible micro-bio-growth (due to improper ventilation) • Consult qualified professional		
Kitchen				
Page 13 Item: 7	Sinks	<ul> <li>Faucet leaks while operating • Consult qualified professional</li> </ul>		
Basement				
Page 14 Item: 2	Smoke Detectors	• none • Recommend, to improve, install additional smoke detectors in proper areas		
Page 16 Item: 10	Closet	• Evidence of water/moisture infiltration from mechanical room (possible micro-bio-growth present, Consult qualified professional)		
Page 17 Item: 11 Mechanical Room		<ul> <li>Evidence of current leak at pressure tank</li> <li>Consult qualified professional</li> </ul>		
Heat/AC				
Page 18 Item: 5	Venting	<ul> <li>Damaged vent pipe (evidence of unsuccessful repairs)</li> <li>Consult qualified professional</li> </ul>		

#### **Exterior Areas**

#### 1. Gutter

Good	Fair	Poor	N/A	None
	Х	Х		

Observations: missing down spouts • poor slope/sagging in some areas • Recommend to improve; install rain gutters & downspouts • Recommend, to improve install extensions to direct water away from structure





missing down spouts

Recommend to improve; install rain gutters & downspouts

#### 2. Eaves & Facia

Good	Fair	Poor	N/A	None
	Х			

Observations: Appears functional • Split/gapped facia • weathered • Consult qualified professional for further evaluation



Split/gapped facia

#### 3. Siding Condition

Good	Fair	Poor	N/A	None
Х	Х			

Materials: Wood/log

Observations: Appears functional • Chinking missing/deteriorating in some areas • Exterior penetrations not sealed to improve caulk/reseal to prevent moisture/insect penetration • Dryer vent cover damaged/ missing • Trees/shrubs overgrown/contact with structure in some areas (recommend trim to prevent damage) • Consult qualified professional

## 522 Puka Puka Avenue, Somewhere, Idaho



Trees/shrubs overgrown/contact with structure in some areas (recommend trim to prevent damage)

Chinking missing/deteriorating in some areas



Dryer vent cover damaged/ missing



Exterior penetrations not sealed to improve caulk/reseal to prevent moisture/insect penetration

#### 4. Doors

Good	ган	F001	IN/A	None	Observations No servan de ser anno ser
			Х		Observations: No screen doors present

#### 5. Window Condition

_ (-	200a	Fair	Poor	N/A	None	
						Observations: Aluminum • torn/damaged/missing screens at some windows
		Χ				
		/\				<ul> <li>condensation present in some windows (seal broken)</li> <li>Consult qualified</li> </ul>
						'
						professional

#### 6. Grounds Electrical

Good	Fair	Poor	N/A	
.,				Observations: Appears functional • exposed romex wiring, (evidence of
Х		X		→ broken insulation) • Consult qualified professional
		•		— broken insulation) * Consult qualified professional

## 522 Puka Puka Avenue, Somewhere, Idaho



exposed unanchored romex wiring, (evidence of broken insulation)

exposed romex wiring, (evidence of broken insulation)

#### 7. Stairs & Handrail

G000	raii	Poor	IN/A	None
Х	Х			

Observations: Appears functional • No hand railing (4 or more steps require a handrail) • Rear concrete steps have hole present, (recommend seal to prevent moisture/insect intrusion) • Consult qualified professional



No hand railing (4 or more steps require a handrail)



Rear concrete steps have hole present, (recommend seal to prevent moisture/insect intrusion)

#### 8. Foundation

Sood Fair Poor N/A None Observations: Appears Functional • Vegetation prevents complete evaluation

#### 9. General Condition

Good	Fair	Poor	N/A	None	$\sim$
Χ					O

Observations: Appears functional

#### Roof

## 1. Roof Condition

Good	Fair	Poor	N/A	None	Matadala Oalda at da naat
					Materials: Gable style roof
X	X				Materials: wood/shake shingles
		•			· Materials. Wood/Sriake Srilligies

Materials: wood/shake shingles
Observations: Appears Functional • Ridge cap nails/staples backing out •
Broken shingle • Metal used as starter course loose,needs reattached •
Consult Qualified Professional for further evaluation



**Appears Functional** 




Metal used as starter course loose,needs reattached



Broken shingle

Ridge cap nails/staples backing out

## 522 Puka Puka Avenue, Somewhere, Idaho



Ridge cap nails/staples backing out

Metal used as starter course loose,needs reattached

## 2. Chimney

Good	Fair	Poor	N/A	None
Х				

Observations: Appears Funtional



**Appears Functional** 

## 3. Flashing

(	Good	Fair	Poor	N/A	None
	Χ				

Observations: Appears functional

#### 4. Vent Caps

Good	Fair	Poor	N/A	None
			Х	

Observations: To improve additional vent installations recommended (proper ventilation adds to the life expectancy of the roof)

## 5. Gutter

Good	Fair	Poor	N/A	None
		Х		

Observations: restricted by debris (recommend clear to improve drainage/flow)



restricted by debris (recommend clear to improve drainage/flow)

## 6. Plumbing vents

Good	Fair	Poor	N/A	None
χ				

Observations:

Appears functional



Appears functional

## 7. Valley

Good	Fair	Poor	N/A	None	Ob
\ <u> \</u>					Observations:
X					<ul> <li>Appears functional</li> </ul>
					Tippodio idilolidilal

#### Attic

## 1. Access

_ (	Good	Fair	Poor	N/A	None	
	Χ					Observations: Appears Functional • Hall access • Attic areas inspected from
	Λ					access only (entry could damage house or property)

#### 2. Exhaust Vent

Good	Fair	Poor	N/A	None
		Х		

Observations: Bath exhaust fan does not vent to the exterior (causes moisture build up/possible dry rot) • Evidence of possible micro-bio-growth (due to improper ventilation) • Consult qualified professional



Bath exhaust fan does not vent to the exterior (causes moisture build up/possible dry rot)

Evidence of possible micro-bio-growth (due to improper ventilation)

#### 3. Insulation Condition

Good F	air	Poor	11/7	None
X				

Materials: blown in fiberglass Materials: appx.12-14 inches Observations: Appears Functional



Appears Functional

## 4. Attic Plumbing

Good	Fair	Poor	N/A	None	Observations, and and functional most of a due to insulation 0 limited assess
Х					Observations: appears functional, most n/a due to insulation & limited access
X					

#### 5. Structure

Good	Fair	Poor	N/A	None	. Observations, and a set to attack
V					Observations: appears functional
X					



appears functional

#### 6. Ventilation

Good	Fair	Poor	N/A	None	
	V				Observations: Appears functional • recommend adding additional vents (to
	X				improve only, adds life to roof covering) • Consult qualified professional



recommend adding additional vents (to improve only, adds life to roof covering)

#### 7. Condition

Good	Fair	Poor	N/A	None	Observations Announce Franctional
Υ					Observations: Appears Functional
$\sim$					

#### Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The insector does not usually test for mold or other hazardous materials. A qualified expert

522 Puka Puka Avenue, Somewhere, Idaho

should be consulted if you would like further testing.

#### 1. Bar

Good	Fair	Poor	N/A	None	Observations Assessed to a time of
Χ					Observations: Appears functional

## 2. Ceiling Fans

Good	Fair	Poor	N/A	None	Observations, Appears functional - Operated
Χ					Observations: Appears functional • Operated

#### 3. Closets

Good	Fair	Poor	N/A	None	Observations Assessed to a time
X					Observations: Appears functiona
A					

## 4. Door Bell

Good	Fair	Poor	N/A	None	Ob
V					Observations: Appears functional
X					

### 5. Doors

Good	Fair	Poor	N/A	None	Ol
					Observations: Appears functional
X					

#### 6. Electrical

Good	Fair	Poor	N/A	None	Ol
					Observations: Appears functional
l X					

#### 7. Fireplace

Good	raii	P001	IN/A	None	Matariala, Linia, Dagas
					Materials: Living Room
			V		
			_ ^		Materials: prefabricated
					Materials. Prefabilitates

Observations: Not scope of inspection • consult qualified professional for

further evaluation



Not scope of inspection

## 8. Smoke Detectors

Good	Fair	Poor	N/A	None	Observations Annager to stieve by Oservated
Y					Observations: Appears functional • Operated

## 522 Puka Puka Avenue, Somewhere, Idaho

#### 9. Window Condition

Good	Fair	Poor	N/A	None
	Χ			

Materials: aluminum

Observations: Appears functional • evidence of condensation at some

windows (Seal broken) • Consult qualified professional



evidence of condensation at some windows (Seal broken)

## 10. Condition

Good	Fair	Poor	N/A	None
Χ				

Observations: appears functional

#### 11. Baths

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears functional

#### 12. Bedrooms

Good	Fair	Poor	N/A	None
Х				

Observations: Appears Functional

#### Kitchen

#### 1. Cabinets

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears functional • Normal wear

#### 2. Counters

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears functional • normal wear

#### 3. Electrical

Good	Fair	Poor	N/A	None
Х				

Observations: Appears functional

## 522 Puka Puka Avenue, Somewhere, Idaho

## 4. GFCI

Good	Fair	Poor	N/A	None	
			Υ		Observations: recommend, consider install GFCI breakers in wet areas

## 5. Garbage Disposal

Good	Fair	Poor	N/A	None	Observations Annagen to attend to a second
Χ					Observations: Appears functional • operated

## 6. Plumbing

Good	Fair	Poor	N/A	None	Observations Assessed to actional
Χ					Observations: Appears functional
X					[ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]

## 7. Sinks

Good	Fair	Poor	N/A	None	
	Χ	Х			

Observations: Faucet leaks while operating • Consult qualified professional



Faucet leaks while operating

## Laundry

## 1. Condition

Good	Fair	Poor	N/A	None	Ob
\/					Observations: Appears functional
X					• •

## 2. Dryer Vent

Good	Fair	Poor	N/A	None	
		\ <u>\</u>			Observations: damaged vent pipe • Consult qualified professional
		l X			



damaged vent pipe

#### 3. Electrical

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears functional

#### 4. Plumbing

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears functional

## **Basement**

#### 1. Electrical

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears Functional

#### 2. Smoke Detectors

Good	Fair	Poor	N/A	None
				Χ

Observations: Recommend, to improve, install C.O detectors • none • Recommend, to improve, install additional smoke detectors in proper areas

#### 3. Stairs & Handrail

Good	Fair	Poor	N/A	None
Х				

Observations: Appears Functional

#### 4. Doors

Good	Fair	Poor	N/A	None
Χ				

Observations: Appear Functional

#### 5. Window Condition

Good	Fair	Poor	N/A	None
	Χ			

Materials: aluminum

Observations: Appears Functional • Open window well; The windows are of egress type, to improve, recommend install a fixed window well ladder and covers (safety) • Consult qualified professional



Open window well; The windows are of egress type, to improve, recommend install a fixed window well ladder and covers (safety)

## 6. Insulation Condition

Good	Fair	Poor	N/A	None	Matarials, Dantial finish ad base on at /aculal cat fully avaluate.
Χ					Materials: Partial finished basement (could not fully evaluate)

## 7. Ceiling Condition

Good	Fair	Poor	IN/A	None	Matariala, du suall
					Materials: drywall
Х					Observations: Appears Functional
					Observations. Appears i unictional

## 8. bedrooms

	Good	Fair	Poor	N/A	None	
ſ	Χ	Χ				Observations: appears functional • windows are not of the egress type

## 9. condition

Good	Fair	Poor	N/A	None	Observations, and a sectional
Χ					Observations: appears functional

## 10. Closet

	Good	Fall	FUUI	IN/A	None	Observations. Evidence of water/ordet we intitude from march and all reserves
Г						Observations: Evidence of water/moisture infiltration from mechanical room
		V	l V			
		Λ	Χ			(possible micro-bio-growth present, Consult qualified professional)
			•	•		(possible fillero-bio-growth present, consult qualified professional)

## 522 Puka Puka Avenue, Somewhere, Idaho



Evidence of water/moisture infiltration from mechanical room (possible micro-bio-growth present, Consult qualified professional)



Evidence of water/moisture infiltration from mechanical room (possible micro-bio-growth present, Consult qualified professional)

#### 11. Mechanical Room

X | None | Observations: Appears functional • Evidence of current leak at pressure tank • Consult qualified professional



Evidence of current leak at pressure tank



Evidence of current leak at pressure tank



Evidence of standing water at pressure tank relief valve

#### Heat/AC

The heating, ventillation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventillation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

#### 1. Heater Condition

	Good	raii	P001	IN/A	None	A			
Γ						Area mechanical room • basement			
	X								
l	/\				1	Type/Year Propane (mfg. date 1990)			
						Observations: Appears Functional • Operated • Recommend HVAC			
						contractor to evaluate (due to age)			
						contractor to evaluate (add to age)			



**Appears Functional** 

## 2. Heater Base

Good	Fair	Poor	N/A	None	Ol
\ <u>/</u>					Observations: Appears functional
Χ					

## 3. Gas Valves

Good	Fair	Poor	N/A	None	. Ob
					Observations: Appears functional
X					' '

## 4. Thermostats

Good	Fair	Poor	N/A	None	
V					Observations: Appears functional • Operated
Χ					

## 5. Venting

Good	ган	FUUI	IN/A	
				Observations: Damaged vent pipe (evidence of unsuccessful repairs) •
		V		
		_ ^		Lonsult qualified professional
			•	— Consult dualifica professional



Damaged vent pipe (evidence of unsuccessful repairs)

## 522 Puka Puka Avenue, Somewhere, Idaho

#### Water Heater

#### 1. Base

Good	ган	FUUI	IN/A	None	· Observations · Augustus from the color date when to all serves have a contract in the color of
					Observations: Appears functional • deteriorated/corrosion present • Consult
	V				
	^				qualified professional
				•	qualifica professional

## 2. Condition

	Good	Fair	Poor	N/A	None Olean Mine College Colleg
		V	Χ		Observations: Evidence of corrosion • Possible nearing end of estimated
L		^	_ ^		useful life expectancy • Consult qualified professional for further evaluation

#### 3. Water Heater Condition

	1 (1)	1 001	1 10// 1	110110	Type: electric
V					
X					Location: Basement • Mechanical Room
					Observations: Apears functional • older unit

#### 4. Number Of Gallons

Good	Fair	Poor	N/A	None	Observations 50 millions (mfm. data 4004)
	Χ				Observations: 52 gallons (mfg. date 1984)

52 gallons (mfg. date 1984)

## 5. Overflow Condition

	Good	Fair	Poor	N/A	None	Matadalar asasas
						Materials: copper
	X					Observations: Appears functional
4				•		- Observations, Appears runctional

#### 6. Plumbing

V	V	⊺ Materials: galvanized
X	X_	Observations: corrosion present (possible di- electrical reaction) dissimilar
		metals • Consult qualified professional for further evaluation

## 522 Puka Puka Avenue, Somewhere, Idaho



corrosion present (possible di- electrical reaction) dissimilar metals

## 7. TPRV

Good	Fair	Poor	N/A	None
X				

Observations: Appears functional

#### Electrical

## 1. Electrical Panel

Good	Fair	Poor	N/A	None	The safe and the second second second second second
Х	Χ	Χ		1	Location north side • Exterior of structure

Observations: appears functional • rust present • missing inside cover • Missing panel cover screws



appears functional



missing inside cover



appears functional

## 2. Main Amp Breaker

Good	Fair	Poor	N/A	None	01
Χ					Observations: 200 amp

## 3. Service

Good	Fair	Poor	N/A	None	Observations Alicensia
Y					Observations: Aluminum
_ ^					

## 4. Breakers

Guuu	ı alı	FUUI	11/7	INOHE	NA-4
					Materials: copper
\/					i Materiale: copper
X					Observations: Appears functional
					J Observations: Appears functional

## 5. Cable Feeds

Good	Fair	Poor	N/A	None	المحدد ومساورا المحددان والمساورا
Χ					Observations: Underground

#### 6. Main Gas Valve Condition

	Guuu	ı alı	FUUI	11//	INOLIG	Lasatiana Duanana
- [						Location: Propane
- 1	\/					
- 1	X					Observations: Appears functional • Propane
ı						Observations. Appears functional • Frogatie

#### Grounds

## 1. Grading

Good	Fair	Poor	N/A	None	Observations Asserted to the Control of the Control
	\ \				Observations: Appears functional • Flat or slopes towards structure in some
	X				areas • To improve; always divert water/moisture away from structure



Flat or slopes towards structure in some areas

## 2. Additional Buildings

Good	Fair	Poor	N/A	None	Oleman Cara National Character
			Х		Observations: Not scope of inspection

## 3. Well condition

Good	Fair	Poor	N/A	None
			Χ	

Observations:

- Not scope of inspectionConsult qualified professional

## Crawlspace

## 1. Foundation Walls

Good	Fair	Poor	N/A	None	Ob
					Observations: appears functional
Х					• •

## 2. Cripple Walls

_	Good	ган	PUUI	IN/A	None	Ola	A	£ 4! 1
ſ						Observations:	Appears	tunctional
ı	Х						• •	



Appears functional

## 3. Ventilation

Good	Fair	Poor	N/A	None
	Χ			

Observations: appears functional • Vents not properly secured, Gaps present due to cable installation allowing insect intrusion,recommend seal/re-attach • Consult qualified professional



Vents not properly secured, Gaps present due to cable installation allowing insect intrusion, recommend seal/re-attach

## 4. Access Panel

Good	Fair	Poor	N/A	None	
Χ					Observations: appears functional • bedroom closet

#### 5. Post and Girders

Good	Fair	Poor	N/A	None	Ol
\ /					Observations: appears functional
Х					' '

#### 6. Foundation Electrical

Good	Fair	Poor	N/A	None	Observations, and a sectional
>					Observations: appears functional
$\sim$					

#### 7. Foundation Plumbing

Good	Fair	Poor	N/A	None	$\sim$
Χ					Or

Observations: appears functional



appears functional

## 8. Insulation Condition

Good	Fair	Poor	N/A	None
	Χ	Х		

Observations: Appears Functional • Only partial insulation installed, (rolls of insulation present) • Consult qualified professional



Only partial insulation installed, (rolls of insulation present)

#### 9. Condition

Good	Fair	Poor	N/A	None
Χ				

Observations: Appears Functional • No vapor barrier present